ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: M118328 Date Received: 01/04/08 Date Extracted: 01/07/08 Date Analyzed: 01/07/08 Matrix: Water Units: ug/L (ppb)

Project: Lab ID: Data File: Instrument:

Client:

Alaskan Copper Works PO M118328, F&BI 801043

801043-01 x10 801043-01 x10.041

ICPMS1 hr

Operator:

Internal Standard: Germanium

% Recovery: 106

Lower Limit: 60

Upper Limit: 125

Concentration Analyte: ug/L (ppb) Chromium 124 Nickel 115 107 Copper Zinc <10

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Alaskan Copper Works Method Blank Client ID: Client: Date Received: Not Applicable PO M118328, F&BI 801043 Project: 01/07/08 Lab ID: 17-493 mb Date Extracted: 01/07/08 Data File: 17-493 mb.008 Date Analyzed:

Matrix: Water Instrument: ICPMS1

Units: ug/L (ppb) Operator: hr

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 104 60 125

<1

Concentration
Analyte: ug/L (ppb)

Chromium <1
Nickel <1
Copper <1

Zinc

ENVIRONMENTAL CHEMISTS

Date of Report: 01/08/08 Date Received: 01/04/08

Project: Metro Self Monitor, PO M118328, F&BI 801043

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 801049-13 (Duplicate)

		Sample	Duplicate	Relative Percent	Acceptan	ce
Analyte	Reporting Units	Result	Result	Difference	e Criteria	<u>i </u>
Chromium	ug/L (ppb)	1.23	1.11	10	0-20	J. Maria
Nickel	ug/L (ppb)	4.39	3.95	11	0-20	450
Copper	ug/L (ppb)	<1	<1	nm	0-20	4.5
Zinc	ug/L (ppb)	1.82	1.50	19	0-20	

Laboratory Code: 801049-13 (Matrix Spike)

naka nata:	Ni Marthin Alkin.			Percent	and the beginning the	
		Spike	Sample	Recovery	Acceptance	е
Analyte	Reporting Units	Level	Result	MS	Criteria	
Chromium	ug/L (ppb)	20	1.23	84	50-150	4.17
Nickel	ug/L (ppb)	20	4.39	76 b	50-150	
Copper	ug/L (ppb)	20	<1	77	50-150	
Zinc	ug/L (ppb)	50	1.82	83	50-150	

Laboratory Code: Laboratory Control Sample

		Spike	Percent Recovery	Acceptance			
Analyte	Reporting Units	Level	LCS	Criteria			
Chromium	ug/L (ppb)	20	102	70-130	ī		
Nickel	ug/L (ppb)	20	103	70-130			
Copper	ug/L (ppb)	20	103	70-130			
Zinc	ug/L (ppb)	50	104	70-130			

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probablility.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

801043		•	SAI	MPLE	CHAI	N OF C	UST	OD	Y	MA	F 1	21-1	24	00	R			AI	3	
Send Report To Green	· 1 -		`	SAMP	LERS	ignature)				7		1			<u>_</u>			AROUND	of	
Send Report To Descout	0 4-1	Hompson		PROT	CT NIA	MENIO						PO	#	_	In					
Company ALASKAN Copper Works			20 20 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0								ADITOTI COM									
Address 628 5	Address 628 S. Handred ST				Metro Self monitor M118328								8	Rush charges authorized by:						
· City, State, ZIP Seattle WA 9834				REMARKS									SAMPLE DISPOSAL Dispose after 30 days							
Phone # 206-5 #-605	3 Fax # 200	6-382-	4309															amples with instru	ıctions	
	- r										ANA	r vei	re p	EQU	ren	רוים				
			1	T			$\vdash \lnot$	T	ml					To Sec	TOT	00		1		
		,				8 2	e	TPH-Gasoline	BTEX by 8021B	VOCs by 8260	8270		3							
				1		# of	TPH-Diesel	logi	80	8	20	ß	3							
Sample ID	Lab ID	Date	Time	Samp	le Type	containers	H.I.	Ö	₹ by	s p	3	HFS	-31					1	Totes	
	,					, "	TP	PH	<u>e</u>	8	SVOCs by		2					Ì		
				<u> </u>				T	B		23	(
M7118328	01	1/4/08	1:30	bfo	20	/						ŀ	1						÷	
•																				
		 							-	\dashv		\dashv				 	\vdash			
												\perp				<u> </u>				
			 							\dashv		\neg				T	+			
																_				
×																1				
			 		<u></u>				\vdash	\dashv		\dashv		-	1	-	\dagger			
		<u> </u>		i			_								_		_			
		1		1					-							Ì				
							\vdash				_			-	 	+	十	 		
				!															,	
		ē.		1								2.1								
Friedman & Bruya, Inc.	11	SIGNATU	JRE			PRIN	r na	ME			T	<u></u>	CC	MP	ANY	7		DATE	TIME	
3012 16th Avenue West	Relinguished b				1	excub		P	PS	ال عد			4	100	ï			1/4/28		
Seattle, WA 98119-2029	Received by:	un 1	w	\rightarrow	777	ilen	_	4	in		\dashv		F	-e 1	3 I	_	7	1/4/08	1:50	
Ph. (206) 285-8282	Relinquished b	y:/		······································		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	-0-				1	1						111 90	1	
Fax (206) 283-5044	Received by:										\dashv			•				-		
FORMS\COC\COC DOC	L				<u> </u>							-						0	. Ц	

Samples received at a 18°C

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

January 8, 2008

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on January 4, 2008 from the Metro Self Monitor, PO M118328, F&BI 801043 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you should have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0108R.DOC